

REPORT of SURVEY for REPAIRS.

No. 266 Survey held at London Date 3^d August 1839
on the Ship Abene Master Rimmer
Tonnage 158 Built at Damen When built 1826
By whom built _____ Owners _____
Port belonging to Griefswold Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____

Original Survey, No. 23 Dated _____ Classed expurgu
Port Guernsey & London 5243.

Repairs At on her last voyage plank shears
up and other defects

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <u>Sufficient</u>
Plank Shears <u>good</u>	Counter <u>good</u>	Sails <u>Good</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, This vessel is now in an efficient condition
as required by the Instructions, for the conveyance of any and perishable cargoes and
may be engaged for Freight

The Amount of Fee.....£ 1 : 1 : - is received by me, W

Committee Minute 9 Aug 1839

Character assigned Fit for service