

REPORT of SURVEY for REPAIRS.

No. 15 Survey held at London Date July 29th 1839
on the Ship Underwood Master Moffatt
Tonnage 315 Built at Ipswich When built 1818
By whom built Jabez Bayley Owners Boodington & Co
Port belonging to London Destined Voyage Samoa
If Surveyed Afloat or in Dry Dock Dukeshore Dry Dock

Original Survey, No. 548, 1865, Dated February 1839 Classed *E1
2965, 3829, 5008,
Port London

Repairs At the present time Copper stripped - caulked from the keel to the wood sheathing on the upper Course - one wood and one Iron Hanging knee to lower Deck shifted and a few of the knees - sheathed with yellow sheet on paper to 13 ft.

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>July 1839</u>	Standing & Running Rigging <u>refitting house</u>

General Observations and Opinion,
as required by the Instructions, In my opinion this ship is fully entitled to remain as at present classed *E1
George Bayley

The Amount of Fee.....£ 1 : 1 : is received by me, AA

Committee's Minute G. Bayley 1839

Character assigned *E1 See repairs
Attest