

# ANNUAL SURVEYS.

5527

No. 722 Survey held at London Date August 10<sup>th</sup> 1839  
 on the Brig Courier Master Laughton  
 Tonnage 168 Built at Liverpool When built 1819  
 By whom built \_\_\_\_\_ Owners West African Co  
 Port belonging to London Destined Voyage Africa  
 If Surveyed Afloat or in Dry Dock Evans Dry Dock

Original Survey, No. 1246, 247 Port of London  
4208, 5513,

1838 Classed A.1 Astoria

The Surveyor is required to state the present Condition of the

|                               |   |                            |
|-------------------------------|---|----------------------------|
| Decks                         | Breasthooks   | Capstan                    |
| Upper Deck Beams & Fastenings | Transoms  | Pumps                      |
| Lower Deck Beams & Fastenings | Timbers of the Frame                                  | Masts, Yards, &c.          |
| Spirkettling                  | Topsides  | Sails                      |
| Plank Shears                  | Wales   | Cables                     |
| Waterways                     | Plank and Treenails<br>(Outside to the Water's Edge.) | Anchors No. of             |
| Hatchway Comings              | Rudder  | Standing & Running Rigging |
|                               | Windlass  | Copper                     |

General Observations and Opinion, Since the date of last report 5<sup>th</sup> 2 pair of Iron knees (bars)  
as required by the Instructions, have been put in & the fastenings have been overhauled  
found good

George Bayley

Committee Minute 13 May 1839

Character assigned A.1 Astoria

No. 127 Survey held at London Date August 10<sup>th</sup> 1839  
 on the Bark Nesbitt Master Simpson  
 Tonnage 245 Built at London When built 1800  
 By whom built Young Owners Nockells  
 Port belonging to London Destined Voyage Jamaica  
 If Surveyed Afloat or in Dry Dock Step<sup>rs</sup> Kings Dry Dock

Original Survey, No. 699, 1791 Port of London  
2726, 3574

1837 Classed A.1

The Surveyor is required to state the present Condition of the

|                               |   |                            |
|-------------------------------|---|----------------------------|
| Decks                         | Breasthooks   | Capstan                    |
| Upper Deck Beams & Fastenings | Transoms  | Pumps                      |
| Lower Deck Beams & Fastenings | Timbers of the Frame                                  | Masts, Yards, &c.          |
| Spirkettling                  | Topsides  | Sails                      |
| Plank Shears                  | Wales   | Cables                     |
| Waterways                     | Plank and Treenails<br>(Outside to the Water's Edge.) | Anchors No. of             |
| Hatchway Comings              | Rudder  | Standing & Running Rigging |
|                               | Windlass  | Copper                     |

General Observations and Opinion, At the present time the Copper repaired - & throughout  
as required by the Instructions, good and efficient condition for remaining as classed A.1

George Bayley

Committee Minute 13 May 1839

Character assigned A.1 Astoria



© 2019

Lloyd's Register  
Foundation