

REPORT of SURVEY for REPAIRS.

5549

JD

No. 109 Survey held at London Date Aug 17 1839
 on the B^t West Indian Master McArthur
 Tonnage 328 Built at Bristol When built 1823
 By whom built _____ Owners Boddytown
 Port belonging to London Destined Voyage Hobart Town
 If Surveyed Afloat or in Dry Dock Landed Dock

Original Survey, No. 100, 1872 Dated 1835 Classed 10 A 1
 Port London

Repairs at the present time stripped - carried from the keel up by recoppering to water

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>1839</u>	Standing & Running Rigging

General Observations and Opinion, This ship is in good and efficient condition
 as required by the Instructions, fully eligible to remain so classed 10 A 1
George Bayley

The Amount of Fee.....£ 1 : 1 : - is received by me, JD

Committee's Minute 20 Aug 1839

Character assigned 10 A 1

