

ANNUAL SURVEYS.

5572

No. 119 Survey held at London Date Aug 27 1839
 on the Ship Lamplade Caroline Master Campbell
 Tonnage 473 Built at Spewich When built 1800
 By whom built Geo Bayley Senr Owners Malcolm
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dowling Dock

Original Survey, No. 2744, 4343 Port of London 1838 Classed F.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

Good *Good* *Good efficient*

General Observations and Opinion,
as required by the Instructions,

*Copper &c rep when necessary it is good
and efficient state of repair for remaining*

Classed F.1

Committee Minute 30th August 1839

Character assigned

F.1

George Bayley

No. 442 Survey held at London Date August 28 1839
 on the Bank City of London Master Antram
 Tonnage 330 Built at Leith When built 1837
 By whom built Rose & Co Owners Johnstone
 Port belonging to London Destined Voyage Honduras
 If Surveyed Afloat or in Dry Dock Globe Dock

Original Survey, No. 3344 Port of London 1837 Classed 12A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank & Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder <i>New Main Piece</i>	Standing & Running Rigging
	Windlass	Copper

Good *Good* *Good and efficient*

General Observations and Opinion,
as required by the Instructions,

*at the present time an additional Kola beam by
2 pair of Hanging Kines put in - 1 pair from hanging
Kines to upper Deck New main piece of Rudder and fitting
as Truss etc - ship is in a good and efficient state
of repair*

Committee Minute 30th August 1839

Character assigned

12 A1

George Bayley
© 2019
Lloyd's Register
Foundation