

ANNUAL SURVEYS.

5580

No. 114 Survey held at London Date Aug 15. 19th 1839
 on the Ship Bengalee Merchant Master _____
 Tonnage 503 Built at Calcutta When built 1812
 By whom built _____ Owners Haweside
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Blackett's Dock

Original Survey, No. 755,2580, Port of LondonFeb 4 1839Classed X. A.

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, at the present time in consequence of having been ashore
 as required by the Instructions, Shipped, & Shakes of Doubling shifted - Beam & Keel rebolts
gripe & Sals-kel refitted, cancelled keel up & reopposed
as before - Surveyor's opinion still eligible to her
original Class X. A. 1

Committee Minute Sept 1839
 Character assigned X. A. 1 George Bayley
Free £ 3. 3. - Recd H.

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Original Survey, No. _____ Port of _____ Classed _____

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions,

Committee Minute _____ 183

Character assigned _____