

REPORT of SURVEY for REPAIRS.

5583

No. 476 Survey held at London Date August 10 1839
 on the Bg Lusitania Master Gibbens
 Tonnage 175 Built at Yarmouth When built 1821
 By whom built _____ Owners Gibbens
 Port belonging to London Destined Voyage Open
 If Surveyed Afloat or in Dry Dock in the Dry Dock

Original Survey, No. 2982, 3570 Dated 1839 Classed A. 1
 Port of London 5494,

Repairs At the present time new Plank Sheer & Sheer stake from the
 Mainmast, forward, eight new stanchions, several Butts
 rebolted & clenched in the ceiling, all the defective beenails
 driven out and caulked from the keel upwards —

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c. <u>Good</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Sails <u>I sufficient</u>
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, The timbers where exposed were sound & good and other
 as required by the Instructions, general appearance very favorable, I am of opinion
is in good condition for the safe conveyance of
dry & perishable cargoes of any kind
A. 1 with the Asterisk

The Amount of Fee.....£ 1 : 1 : — is received by me, W. H.

Committee's Minute 6 Sept 1839

Character assigned A. 1 under repair