

REPORT of SURVEY for REPAIRS.

No. 5608 Survey held at London Date July 17 1838
on the Ship Mercy Master Whalley
Tonnage 416 Built at Chepstow When built 1806
By whom built _____ Owners Daniel & Co
Port belonging to London Destined Voyage Baltimore
If Surveyed Afloat or in Dry Dock Blackwall Dry Dock

Original Survey, No. _____ Dated 1838 Classed A.1
Port London

Repairs *at the present time Hood ends and Keelson
listed and caulked - Two planks shifted on
Starboard side aft forward - Tankers fair
condition Sheathed with yellow metal to
Wale*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
as required by the Instructions,

*In my opinion this ship is fully eligible
to remain as classed A.1*

George Bayley

The Amount of Fee.....£ : : is received by me,

Committee Minute _____ 18 _____

Character assigned _____