

ANNUAL SURVEYS.

5624

No. 634 Survey held at London Date Sept 7 1839
 on the City of Edinburgh Master Hunter
 Tonnage 454 Built at Leith When built 1824
 By whom built Owners Hunter
 Port belonging to Leith Destined Voyage
 If Surveyed Afloat or in Dry Dock Leith Dock

Original Survey, No. 3105, 3273 Port of London March 1838 Classed F.1
5062, & see Annexed Survey

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>rebolted</u>	Capstan <u></u>
Upper Deck Beams & Fastenings <u>Firm</u>	Transoms <u></u>	Pumps <u></u>
Lower Deck Beams & Fastenings <u>do</u>	Timbers of the Frame <u></u>	Masts, Yards, &c. <u></u>
Spirkettling <u></u>	Topsides <u>Good</u>	Sails <u></u>
Plank Shears <u></u>	Wales <u></u>	Cables <u></u>
Waterways <u>Effectually bolted</u>	Plank and Treenails (Outside to the Water's Edge) <u></u>	Anchors No. of <u></u>
Hatchway Comings <u></u>	Rudder <u></u>	Standing & Running Rigging <u></u>
	Windlass <u></u>	Copper <u></u>

General Observations and Opinion,
 as required by the Instructions

Since the date of the report in August 1838. 3 pair of Stuffs &
 1 pair of Iron Hanging knees have been put in
 & the lower deck waterway bolted horizontally through
 the side - She is now made secure in my opinion eligible
 to be registered to the Class F.1

Committee Minute 17 Sept 1839

Character assigned F.1 ready to repair George Bayley

No. 168 Survey held at London Date Sept 7 1839
 on the Ship Castle Lachlan Master Bruce
 Tonnage 435 Built at Greenock When built 1811
 By whom built Owners Dawson & Co
 Port belonging to London Destined Voyage to India
 If Surveyed Afloat or in Dry Dock Duke Street Dock

Original Survey, No. 612, 1752 Port of London 1838 Classed F.1
3708, 4317, 4643, 5513,

The Surveyor is required to state the present Condition of the

Decks <u></u>	Breasthooks <u></u>	Capstan <u></u>
Upper Deck Beams & Fastenings <u></u>	Transoms <u></u>	Pumps <u></u>
Lower Deck Beams & Fastenings <u></u>	Timbers of the Frame <u></u>	Masts, Yards, &c. <u></u>
Spirkettling <u></u>	Topsides <u></u>	Sails <u></u>
Plank Shears <u></u>	Wales <u></u>	Cables <u></u>
Waterways <u></u>	Plank & Treenails (Outside to the Water's Edge) <u></u>	Anchors No. of <u></u>
Hatchway Comings <u></u>	Rudder <u></u>	Standing & Running Rigging <u></u>
	Windlass <u></u>	Copper <u></u>

General Observations and Opinion,
 as required by the Instructions

Since the date of last annual survey a Poop (of Iron)
 has been put to her and firmly secured -

Committee Minute 17 Sept 1839

Character assigned F.1 ready to repair George Bayley



© 2019

Lloyd's Register
 Foundation

LDN606-0071