

# ANNUAL SURVEYS.

5626

No. 10 Survey held at London Date Sept 9 1839  
 on the Ship Dale Park Master Snell  
 Tonnage 402 Built at London When built 1828  
 By whom built \_\_\_\_\_ Owners Davidson  
 Port belonging to London Destined Voyage Jamaica  
 If Surveyed Afloat or in Dry Dock Globe Dock

Original Survey, No. 958, 3611, Port of London Jan 4 1839 Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

*Good* *Good* *Good & efficient*  
*Good - 24 of 1833?*

General Observations and Opinion, Boards & Copper examined found in good condition  
 as required by the Instructions, In my opinion she is eligible to remain as  
Depot 12 A 1  
George Bayley

Committee Minute 14 Sept 1839

Character assigned 12 A 1

No. 14 Survey held at London Date Sept 9 1839  
 on the Ship Thomas Blyth Master Roe Crowley  
 Tonnage 370 Built at Seychelles When built 1837  
 By whom built \_\_\_\_\_ Owners Blyth & Co  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Ship "King" Dry Dock

Original Survey, No. 4110, 4865 Port of London Jan 4 1839 Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank & Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

*Good* *Good* *Good & efficient*  
*Good & efficient*  
*Good & efficient*  
*Up 1839 Good*

General Observations and Opinion, False keel refastened - Copper overhauled  
 as required by the Instructions, repaired when needed - In my opinion  
she is eligible to remain as a depot 10 A 1

Committee Minute 14 Sept 1839

Character assigned 10 A 1

George Bayley