

REPORT of SURVEY for REPAIRS.

No. 5632 Survey held at London Date August 20th 1839
 on the Bg British Queen Master McKleish
 Tonnage 152 Built at Kincaidine When built 1830
 By whom built _____ Owners McKleish
 Port belonging to Kincaidine Destined Voyage Vera Cruz
 If Surveyed Afloat or in Dry Dock on the Mays

Original Survey, No. _____ Dated 1830 Classed A 1
 Port of Seith

Repairs Caulked from the keel to the gunwale and
Clipped over paper

The Surveyor is also required to state the present Condition of the

| | | |
|-------------------------------|---|-------------------------------|
| Decks | Transoms | Windlass |
| Upper Deck Beams & Fastenings | Timbers of the Frame | Capstan |
| Lower Deck Beams & Fastenings | Topsides | Pumps |
| Spirkettling | Wales | Masts, Yards, &c. <u>Good</u> |
| Plank Shears <u>Good</u> | Counter <u>Good</u> | Sails <u>Efficient</u> |
| Waterways | Plank & Treennails (Outside to the Water's Edge) | Cables |
| Hatchway Comings | Rudder | Anchors No. of _____ |
| Breasthooks | Copper | Standing & Running Rigging |

General Observations and Opinion, In a very high state of efficiency & may retain
 as required by the Instructions, her present class

[Signature]

The Amount of Fee £ : : is received by me,

Committee's Minute _____ 18 _____

Character assigned _____

LON606-0082