

REPORT of SURVEY for REPAIRS.

5658

Handwritten signature/initials

No. 340 Survey held at London Date Sept 26 1839
 on the By Alfred Master _____
 Tonnage 135 Built at Alton When built 1819
 By whom built _____ Owners African Company
 Port belonging to London Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock in the Dry Dock

Original Survey, No. 1030, 2334 Dated 1837 Classed A, 1
3326,
 Port London

Repairs *At the present time two new strokes of Wale, & two below the Wale, all the H.P. Beams fastenings rebitted, three new star tions all the benches examined caulked from the Keel upwards & a general over haul Capped over Tilted two strokes in the Wale —*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,


The timbers were exposed round & good and is in fit condition for the safe carriage of dry & perishable cargoes and may continue A.1

Handwritten signature

The Amount of Fee.....£ — : 10: 6 is received by me, *Handwritten initials*

Committee's Minute 27th Sept. 1839

Character assigned A.1 *Handwritten*



CON606-0113