

ANNUAL SURVEYS.

5690

No. 313 Survey held at London Date Sept 26 18 39
 on the Ship London Master Kent
 Tonnage 441 Built at London When built 1813
 By whom built _____ Owners H. J. J. J.
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock clap King Dry Dock

Original Survey, No. 1799, 2656 Port of London Nov. 1838 Classed A.1

The Surveyor is required to state the present Condition of the

| | | |
|-------------------------------|---|------------------------------------|
| Decks | Breasthooks | Capstan |
| Upper Deck Beams & Fastenings | Transoms | Pumps |
| Lower Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Spirketting | Topsides | Sails |
| Plank Shears | Wales | Cables |
| Waterways | Plank and Treenails (Outside to the Water's Edge.) | Anchors No. of |
| Hatchway Comings | Rudder <u>New Main Piece 1839</u> | Standing & Running Rigging |
| | Windlass <u>Good</u> | Copper <u>rep^d 1839</u> |

General Observations and Opinion, In my opinion this ship is fully eligible to
 as required by the Instructions, be present class A.1
George Bayley

Committee Minute 4 Oct 1839
 Character assigned A.1
LB

No. 764 Survey held at London Date Sept 26 18 39
 on the Bk Miranda Master Lowell
 Tonnage 300 Built at Bristol When built 1828
 By whom built _____ Owners Bateman
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Globe Dock

Original Survey, No. 390 Port of London, Ply. 97. Lon. 3634. 1837 Classed 10 A.1

The Surveyor is required to state the present Condition of the

| | | |
|-------------------------------|---|----------------------------|
| Decks | Breasthooks <u>some bolts shifted</u> | Capstan |
| Upper Deck Beams & Fastenings | Transoms | Pumps |
| Lower Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Spirketting | Topsides | Sails |
| Plank Shears | Wales | Cables |
| Waterways | Plank and Treenails (Outside to the Water's Edge.) | Anchors No. of |
| Hatchway Comings | Rudder | Standing & Running Rigging |
| | Windlass | Copper |

General Observations and Opinion, at the present time generally abackhailed and
 as required by the Instructions, several breast hook bolts shifted - in my opinion
this for the present eligible to the class A.1
George Bayley

Committee Minute 4 Oct 1839
 Character assigned A.1
LB

1710-900N