

# REPORT of SURVEY for REPAIRS.

5723

No. 165 Survey held at London Date October 11 1839  
 on the Bk Isabella Master V Samson  
 Tonnage 323 Built at Whitby When built 1827  
 By whom built \_\_\_\_\_ Owners H Wilson  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1175, 2920 Dated 1837 Classed 10 A 1  
 Port of London, Plymouth 195, London 3732,

## Repairs

In January last in consequence of having been on shore  
 Bottom stripped, three planks shifted in the Bottom  
 partly renewed, caulked from the Keel to the  
 Gunwale and tipped over Boardails Tett

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c. <u>Good</u>
Plank Shears	Counter	Sails <u>Efficient</u>
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,  
 as required by the Instructions,

This vessel is altogether in a very efficient state  
 no appearance of working or decay & I am of opinion  
 is fit for the safe conveyance of dry & perishable  
 cargoes to & from all parts of the World, and may  
 be classed A 1 with the Notebooks

The Amount of Fee.....£ 2 : 2 : - is received by me, H Wilson

Committee's Minute 14 Oct 1839

Character assigned A 1 Antic - minor repairs

60N606-0184