

REPORT of SURVEY for REPAIRS.

5747
No. 531 Survey held at London Date January 14th 1837
on the Bg Andrew M^r Kear Master J Bulten
Tonnage 220 Built at Leith When built 1825
By whom built _____ Owners G Rouby
Port belonging to London Destined Voyage Odessa
If Surveyed Afloat or in Dry Dock in the Ways

Original Survey, No. _____ Dated _____

Port of London

Repairs. *At the present time the whole of the upper and lower deck fastenings driven out and rebolted, caulked all over, an additional piece put on the sternpost, and repaired over paper.*

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
Spirketting _____
Plank Shears _____
Topsides _____
Upper Deck with its Appendages _____
Lower Deck Fastenings _____

Good

Wales _____
Counter _____
Plank and Treenails _____
(Outside to the Water's Edge)
Rudder _____
Windlass _____
Capstan _____

Good

General Observations and Opinion, *In good condition both in the hull & stores as required by the Instructions, fit for the safe conveyance of dry & perishable cargoes and may continue her present class A.*

The Amount of Fee £ : : is received by me.

Committee Minute _____ 183 _____

Character assigned _____



© 2019

Lloyd's Register Foundation