

ANNUAL SURVEYS.

No. 5784 Survey held at London Date Jan 4 29 1839
 on the B^s Scout Master _____
 Tonnage _____ Built at Paris When built _____
 By whom built _____ Owners Hackwood & Co
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Evans Dock

Original Survey, No. none Port of _____ Not Classed

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails <u>Bottom Plank good</u> (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, At the present time bottom caulked & recoppered upon felt to
 as required by the Instructions, the keel George Bayley

Committee Minute _____ 183

Character assigned _____



29/01/2019

Lloyd's Register
Foundation

LON606-0253