

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date Nov 9 1839
 on the Ship Sabella Anna Master _____
 Tonnage 225 Built at Prize When built _____
 By whom built _____ Owners James Wigham & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock West India Dock

Original Survey, No. _____ Dated _____ Classed A.
 Port _____

Repairs In March last, had new Decks. Waterways. Plank sheers
 Topsides & new Beams. a range of Iron Hanging
 knees and Staple Standards. 1 ^{New Deck} ~~Additional~~ Breast Hook
 2 new putches - New lower Deck knee bolts. Hood iron rebolted
 2 knees refitted New pumps - Plank under and
 bro fast Timber shifts. Copper lined and sheathed
 Repair to Hull amounting to £1018 exclusive of Copper
 & Tack
 In 1837 - Bottom Stoppers &c amounting to £390 -
 exclusive of Copper & Tack

The total amount of Repairs to Hull & Materials 1837-1839
 amount is £2354. odd as per Bills produced

The Surveyor is also required to state the present Condition of the

Decks <u>New 1839</u>	Transoms _____	Windlass _____
Upper Deck Beams & Fastenings <u>New 1839</u>	Timbers of the Frame } <u>Good when</u>	Capstan _____
Lower Deck Beams & Fastenings <u>See</u>	Topsides } <u>New 1839</u>	Pumps _____
Spirkettling <u>New 1839</u>	Wales } <u>Good</u>	Masts, Yards, &c. } <u>Good and</u>
Plank Shears _____	Counter } <u>Good</u>	Sails } <u>efficient</u>
Waterways _____	Plank and Treennails (Outside to the Water's Edge)	Cables _____
Hatchway Comings _____	Rudder <u>Good</u>	Anchors No. of _____
Breasthooks <u>Good</u>	Copper _____	Standing & Running Rigging _____

General Observations and Opinion,
 as required by the Instructions,

The appearance of this ship on deck and
 below is now very fine and substantial
 Her waterway seams & joints are firm and unbroken
 & so firm that I can see she appears to fit for the
 conveyance of my and suitable cargo to & from
 all parts of the world eligible to be visited T. A. I.

The Amount of Fee £ : : is received by me,

Committee's Minute 12 Nov 1839

Character assigned Fit for service - need repair

Nov 11. 1839

S. Williams

4. 1839

10

Bill of Exchange



© 2019

Lloyd's Register
Foundation