

REPORT of SURVEY for REPAIRS.

5874

No. 10 Survey held at London Date Nov^r 26th 1839
 on the Bk Florence Master Davis
 Tonnage 179 Built at Farmouth When built 1829
 By whom built - Owners Ried Ho
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Williams' Dock

Original Survey, No. 37 Dated - Classed 12 A 1
 Port Cochin London 4475, 4834, 5057

Repairs At present time in consequence of damage. New
 Stern timbers. Stern, after end of deck, after shifts of topsides,
 plack, stripped bottom caulked and reoppered to the wales

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c. <u>Sufficient</u>
Plank Shears	Counter	Sails <u>Good</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, as required by the Instructions, The timbers exposed in performing Repairs
proved very sound & good is now in a good sufficient
state and may be continued as closed

The Amount of Fee.....£ 1 : 1 : - is received by me, George Bayley

Committee's Minute Dec 18 39

Character assigned 12 A 1 revised Davis

Lucy Special by Mr Bayley
 £2.2

G. F. SKYFANG, PRINTER, FARRINGTON STREET, LONDON.



© 2019

Lloyd's Register
 Foundation

LONG66-6351