

ANNUAL SURVEYS.

5893

No. _____ Survey held at London Date Dec 6 1839
 on the Ship Roberts Master H. Elder
 Tonnage 723 Built at Calcutta When built 1815
 By whom built _____ Owners Elder & Co
 Port belonging to London Destined Voyage South Australia
 If Surveyed Afloat or in Dry Dock Blackett's Dock

Original Survey, No. _____ Port of London October 1838 Classed F. A. 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>cut bowsprit</u>
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>raised 2 strikes - fresh below</u>

General Observations and Opinion, At the present time overhauled aloft Topsides caulked
 as required by the Instructions, some additional Bolts put into fore part of keel
This in my opinion eligible to remain as classed F. A. 1

Committee Minute _____ 183

Character assigned _____

George Bayley

No. _____ Survey held at London Date Dec 7 1839
 on the Ship Prince George Master Young
 Tonnage 482 Built at Bristol When built 1830
 By whom built _____ Owners Homes?
 Port belonging to London Destined Voyage Transport
 If Surveyed Afloat or in Dry Dock Witcher's Dock

Original Survey, No. 1423, 2914, 4511 Port of London 1830 Classed 11 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>Good</u>

General Observations and Opinion, In my opinion this ship is eligible to remain
 as required by the Instructions, as at present classed 11 A 1

Committee Minute 13 Dec 1839

Character assigned 11 A 1

George Bayley



© 2019

Lloyd's Register
Foundation

Oct 12

9 repairs

2 animals

11



© 2019

Lloyd's Register
Foundation