

REPORT of SURVEY for REPAIRS.

5919

Expressing

No. _____ Survey held at London Date Dec 12 1839
 on the Bk John Willis Master J Willis
 566 Tonnage 320 Built at Sunderland When built 1839
 By whom built Stamson Owners Willis & Co
 Port belonging to London Destined Voyage Demerara
 If Surveyed Afloat or in Dry Dock in the Dry Dock

Original Survey, No. 1466 Dated _____ Classed 10 A 1
 Port of Sunderland

Repairs At the present time sheathed with yellow metal over paper

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <u>Good</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Sails <u>Efficient</u>
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, Is in a very efficient state throughout & appears
 as required by the Instructions, eligible to his present Class

W. Middleton

The Amount of Fee.....£ 5 0 0 is received by me, J Willis

Committee's Minute _____ 18 _____

Character assigned See Sunderland 1466



60606-0398