

REPORT of SURVEY for REPAIRS.

No. 454 Survey held at Smith Date 6 Dec 1839
on the Amphitrite Master Ellis
Tonnage 140 Built at London When built 1820
By whom built — Owners Phillips
Port belonging to London Destined Voyage —
If Surveyed Afloat or in Dry Dock Hutchins

Original Survey, No. 1802, 2684, Dated 3447, 4023, 4788, Classed A. R.
Port London

Repairs

At the present time about 20 new Bow timbers, Stave
timbers, the fore part of the cutting the fore end of deck
two new Breast Hooks, the knees of the Hold Beams
rebolled.

20 Feb 1840 the above repairs were not quite finished
and all Lamp present

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting <u>good</u>	Wales <u>good</u>	Masts, Yards, &c. <u>Sufficient</u>
Plank Shears	Counter	Sails <u>and good</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
as required by the Instructions,

As in an efficient state of repair fit for
the conveyance of any species of cargo to and
all ports of the world and may in my opinion be continued
is cleared.

The Amount of Fee.....£ — : 10: 6 is received by me,

Committee's Minute 31 Dec 1839

Character assigned A. R.