

ANNUAL SURVEYS.

5931

No. 149 Survey held at Sunderland Date Dec 23 1839
 on the By Africa Master Baxter
 Tonnage 277 Built at Sunderland When built 1835
 By whom built _____ Owners Wales
 Port belonging to Sunderland Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock in the Dry Dock

Original Survey, No. Sunderland 237 Port of Liverpool Jan. 1839 Classed A 1
2668

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, At the present time Bottom examined,
 as required by the Instructions, is in a very efficient state and may continue
her present class -

Committee Minute 31 Dec 1839

Character assigned A 1

No. 474 Survey held at Sunderland Date Dec 27 1839
 on the By Hope Master Nichols
 Tonnage 130 Built at Plymouth When built 1835
 By whom built _____ Owners Brown
 Port belonging to Cardigan Destined Voyage Eastwards
 If Surveyed Afloat or in Dry Dock in the Ways

Original Survey, No. 12 Port of Cardigan London 4103 Classed E 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, Ship in good condition for the safe conveyance of cargoes
 as required by the Instructions, not liable to sea damage and may continue as
Classed E 1

Committee Minute 31 Dec 1839

Character assigned E 1



© 2019

Lloyd's Register
Foundation