

ANNUAL SURVEYS.

5983

No. 230 Survey held at Louth Date January 3 1840
 on the Ship Tigis Master Thomas Simmons
 Tonnage 426 Built at Scarbro When built 1835
 By whom built Tindall Owners Tindall
 Port belonging to Scarbro Destined Voyage Ceylon
 If Surveyed Afloat or in Dry Dock Scrubble Lough

Original Survey, No. 4368 Port of London 1838 Classed 12A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions,

*At the present time caulking rule by
 ex Loppin she is in many opinion eligible
 to her present class 12A1*

Committee Minute 17 Dec 1840

Character assigned 12A1

No. 111 Survey held at Bristol Date Jan 4 1840
 on the Back Milford Master Davison
 Tonnage 262 Built at Bideford When built 1838
 By whom built Owners Cory
 Port belonging to Bristol Destined Voyage
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 114 Port of Bideford Jan 4 1839 Classed 12A1
Bristol 364,

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions,

*The Timbers of the Frame and the Floors are not squared
 as required by the rules for 12A The keel appears to be
 weak as there are indications of considerable movement
 aloft & made a great deal of water during the last
 voyage - She is going into dock to examine her bottom & caulk
 her Topside - From what could be seen of
 her frame & Floors she appears to be barely eligible
 to 12A1*

Committee Minute 17 Dec 1840

Character assigned 12A1