

# REPORT of SURVEY for <sup>topping</sup> REPAIRS.

No. 462 Survey held at London Date Jan 7/18 1840  
 on the Bark Luddow Master Thos Brunton  
 Tonnage 287 Built at Sunderland When built 1832  
 By whom built \_\_\_\_\_ Owners Jno Graham  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock New Crane Dock

Original Survey, No. 632,3583 Dated June 1839 Classed 11A1  
5340.  
 Port London

Repairs at the present time caulked from keel up and  
sheathed with yellow sheeted copper to 12 feet

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>Yell 1840</u>	Standing & Running Rigging

General Observations and Opinion,  
 as required by the Instructions,

In my opinion this ship is eligible to remain  
as classed 11A1

George Bayley

The Amount of Fee.....£ 1 : 1 : — is received by me, HA

Committee's Minute 28th Jan 1840

Character assigned 11A1 secured sheathed