

Fulmar

6034

REPORT of SURVEY for REPAIRS.

Sparring

No. 502 Survey held at London Date Jan^{ry} 11 1840
on the Bk Emma Master Munn

Tonnage 407 Built at Newcastle When built 1836

By whom built _____ Owners Munn & Co x

Port belonging to London Destined Voyage Peilon

If Surveyed Afloat or in Dry Dock London Dock

Original Survey, No. 470 Dated _____ Classed O A 2

Port Newcastle

Repairs In November 1830 Caulked & Spurred

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of <u>2 Bowers 1 Sm 2 Hedge</u>
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, In a very efficient state and I am of opinion may
as required by the Instructions, raised to O A 1

W. Munn

The Amount of Fee.....£ 1 : 1 : - is received by me, *W. Munn*

Committee's Minute 7th Feby 1840

Character assigned O A 1 Record Copper



© 2019 Lloyd's Register Foundation