

Annual REPORT of SURVEY for REPAIRS.

6042

No. _____ Survey held at London Date Feb 3 - 7 18 40
 on the B^y Whys Master Piley
 Tonnage 181 Built at Yarmouth When built 1829
 By whom built _____ Owners Chodwick
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Yard Dock

Original Survey, No. Blyde 68, 4828 Dated 1838 Classed 12 A 1
 Port London

Repairs

Repaired Bulwarks and shifted the broken
 Stanchions repaired the other damages
 sustained - Caulked aloft repaired
 Copper

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>Feb 1840</u>	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

In my opinion she is eligible to
 remain as classed 12 A 1

George Bayley

The Amount of Fee.....£ _____ is received by me,

Committee's Minute

Character assigned

11th Feb 1840
12 A 1

