

ANNUAL SURVEYS.

6090
H

No. Survey held at London Date Feb 22 1840
 on the Bs Richmond Hill Master Young
 Tonnage 234 Built at Wb When built 1828
 By whom built Owners Davison
 Port belonging to London Destined Voyage Samaria
 If Surveyed Afloat or in Dry Dock Duke Street Dock

Original Survey, No. 892, 1912, Port of London August 1839 Classed A.1
2650, 2948, 3332, 3774, 4158, 5524.

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>Overhauling</u>
Spirketting	Topsides	Sails <u>Good and</u>
Plank Shears	Wales	Cables <u>efficient</u>
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of <u> </u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>Rep 1840</u>

General Observations and Opinion, In my opinion this ship is eligible to
 as required by the Instructions, remain as clasped A.1

Committee Minute 25th Feb 1840
 Character assigned A.1
 George Bayley

No. Survey held at Date 18
 on the Master
 Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Original Survey, No. Port of Classed

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u> </u>
Spirketting	Topsides	Sails <u> </u>
Plank Shears	Wales	Cables <u> </u>
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of <u> </u>
Hatchway Comings	Rudder	Standing & Running Rigging <u> </u>
	Windlass	Copper <u> </u>

General Observations and Opinion,
 as required by the Instructions,

Committee Minute 1833
 Character assigned