

# ANNUAL SURVEYS.

6102

No. 191 Survey held at London Date Feb'y 26 1840  
 on the Bg Agnes Master Adams  
 Tonnage 213 Built at Dunbarton When built 1825  
 By whom built \_\_\_\_\_ Owners Bullock & Co  
 Port belonging to London Destined Voyage Spain  
 If Surveyed Afloat or in Dry Dock in the London Dock

Original Survey, No. Liverpool 706, 3860, 5370 Port of London 1839 Classed A.1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Firm</u>	Transoms <u>"</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>stand as when seen</u>	Masts, Yards, &c. <u>"</u>
Spirkettling _____	Topsides <u>Good</u>	Sails <u>Well found</u>
Plank Shears _____	Wales _____	Cables _____
Waterways _____	Plank and Treenails <u>"</u> <small>(Outside to the Water's Edge.)</small>	Anchors No. of _____
Hatchway Comings _____	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
	Windlass <u>"</u>	Copper _____

General Observations and Opinion, In good condition for the safe conveyance of Dry  
 as required by the Instructions, and perishable cargoes and may continue in her  
present Class

Committee Minute 28th Feb'y 1840

Character assigned A.1

No. 443 Survey held at London Date Feb'y 26 1840  
 on the Bk Royal Tar Master M Bell  
 Tonnage 315 Built at Sunderland When built 1836  
 By whom built \_\_\_\_\_ Owners W Ash  
 Port belonging to Exeter Destined Voyage Halifax  
 If Surveyed Afloat or in Dry Dock in the St Katherine's Dock

Original Survey, No. 488 Port of Sunderland 1836 Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkettling <u>Good</u>	Topsides _____	Sails <u>Well found</u>
Plank Shears _____	Wales <u>Good</u>	Cables <u>found</u>
Waterways <u>Firm</u>	Plank and Treenails _____ <small>(Outside to the Water's Edge.)</small>	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper <u>in 1836</u>

General Observations and Opinion, At the present time caulked and in every respect  
 as required by the Instructions, in very efficient state to retain her present Class

Committee Minute 28th Feb'y 1840

Character assigned 10 A 1

