

ANNUAL SURVEYS.

6124

No. 170 Survey held at London Date Feb 22 18 40
 on the St Margaretta Master Barckman
 Tonnage 369 Built at Sweden When built 1806
 By whom built _____ Owners Wm H. Co Thomson
 Port belonging to Batavia Destined Voyage Batavia
 If Surveyed Afloat or in Dry Dock Dowson's Dock

Original Survey, No. 2705, 4022, Port of London May 1839 Classed X E 1
5207

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions

At the present time several planks shifted in the Topsides - She is now in an efficient state for remain as classed

Cautioned to keep up

Committee Minute 6th March 1840

Character assigned First Category
LB

George Bayley

No. _____ Survey held at London Date Feb 26 18 40
 on the Brig Harriet Master Douglas
 Tonnage _____ Built at Sweden When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage Montreal
 If Surveyed Afloat or in Dry Dock Dowson's Dock

Original Survey, No. _____ Port of _____ Classed _____

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions

This vessel was cautioned keel up over all

Committee Minute _____ 183 _____

Character assigned _____

George Bayley



© 2019

Lloyd's Register
 Foundation