

ANNUAL SURVEYS.

6291

No. 456 Survey held at London Date April 12 1840
on the Brig Claremont Master Maxwell
Tonnage 266 Built at Shields When built 1833
By whom built _____ Owners J. Hopkinson
Port belonging to London Destined Voyage Camerara
If Surveyed Afloat or in Dry Dock West India docks.

Original Survey, No. 1374 Port of Liverpool, Lon. 39° 5', 49 53 Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Good</u>	Capstan _____
Upper Deck Beams & Fastenings <u>"</u>	Transoms <u>"</u>	Pumps _____
Lower Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Masts, Yards, &c. _____
Spirketting <u>"</u>	Topsides <u>"</u>	Sails <u>Good & Efficient</u>
Plank Shears <u>"</u>	Wales <u>"</u>	Cables _____
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of _____
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging _____
	Windlass <u>"</u>	Copper _____

General Observations and Opinion,
as required by the Instructions,

This vessel stands unmarckably well, there is not the least appearance of movement in any part, and in my opinion may remain as clasied 10 A 1

Committee Minute 24th April 1840

Character assigned 10 A 1

Wm. G. Clark

No. _____ Survey held at London Date April 18 1840
on the Owen Glendower Master Pullock
Tonnage 352 Built at Blackwall When built 1839
By whom built Green Wiggins & Green Owners W. Green
Port belonging to London Destined Voyage Bengal
If Surveyed Afloat or in Dry Dock Green Wiggins & Green docks.

Original Survey, No. _____ Port of _____ Classed _____

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirketting _____	Topsides _____	Sails <u>Good and Efficient</u>
Plank Shears _____	Wales _____	Cables _____
Waterways _____	Plank and Treenails _____ (Outside to the Water's Edge.)	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper _____

General Observations and Opinion,
as required by the Instructions,

The Ship is in a very excellent state, and in my opinion may Remain as clasied 12 A 1

Committee Minute _____ 183

Character assigned _____



© 2019

Lloyd's Register
Foundation