

REPORT of SURVEY for REPAIRS.

63444

No. 103 Survey held at London Date 22nd April 1840
 on the Barque Himalaya Master _____
 Tonnage 477 Built at Sunderland When built 1840
 By whom built _____ Owners Author
 Port belonging to London Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Seemanns dock

Original Survey, No. 1616 Dated _____ Classed 10 A 1

Port Sunderland

Repairs At the present time, Sheathed with yellow metal on paper

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears <u>Good</u>	Counter <u>Good</u>	Sails <u>Good</u>
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
as required by the Instructions,

This appears to be a very good 10 year ship

Robert Clark

The Amount of Fee.....£ _____ is received by me,

Committee's Minute 8th May 1840

Character assigned 10 A 1 Good Sheathed

