

REPORT of SURVEY for REPAIRS.

6355

[Signature]

No. _____ Survey held at London Date July 27 1839
 on the Ship Lady Amhurst Master _____
 Tonnage 430 Built at India Calcutta When built 1824 P. Register AA
 By whom built _____ Owners C. Enderby
 Port belonging to London Destined Voyage South Sea Faring
 If Surveyed Afloat or in Dry Dock Shipⁿ Furlings Dry Dock

Original Survey, No. None Dated _____ Classed _____
 Port _____

Repairs *At the present time Shippers called for the keel up
 brood the upon Patent Hair & Coppered to the water
 Poop & Inceente Decks doubled - generally overhauled*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c. <i>Constraining</i>
Plank Shears <i>Good</i>	Counter <i>Good</i>	Sails <i>Putting the</i>
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables <i>Woke into an</i>
Hatchway Comings	Rudder	Anchors No. of <i>efficient State</i>
Breasthooks	Copper <u>1839</u>	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

*In my opinion the Ship is fit for the conveyance of
 dry and perishable cargoes to & from all parts of the world
 & is entitled to be classed ^{2^d} F.*

George Bayley

The Amount of Fee.....£ 2 : 2 : - is received by me, *AA*

Committee's Minute 12th May 1840

Character assigned AA, 1st class

