

ANNUAL SURVEYS.

6476

No. 480 Survey held at London Date June 15th 1840
 on the Bk Royal Consort Master J. Mosen
 Tonnage 524 Built at Sunderland When built 1840
 By whom built _____ Owners H. Metcalf
 Port belonging to Newcastle Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Sunder Dock

Original Survey, No. 1657 Port of Sunderland Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, At the present time sheathed with yellow metal
 as required by the Instructions, and is altogether in a very efficient state

Committee Minute 23rd June 1840

Character assigned 10 A 1 seen sheathed in
ALB

No. 486 Survey held at London Date June 20th 1840
 on the Ship Royal George Master Richard
 Tonnage 406 Built at Yarm When built 1820
 By whom built _____ Owners Wm. D. & Co.
 Port belonging to London Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock in the London Dock

Original Survey, No. 859, 787 Port of London 1030 Classed Proton 6 yrs A1
2565, 4355

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, Is in a very efficient state throughout the appearance
 as required by the Instructions, of wearings or decay and may retain her present class

Committee Minute 23rd June 1840

Character assigned Revised 10 A 1
ALB



© 2019

Lloyd's Register
Foundation

6800-809 NO7