

REPORT of SURVEY for REPAIRS.

No. 6505 Survey held at MDW Date 18 Sep^r 1839
 on the Bk "Brightman" Master Nockels
 Tonnage 384 Built at Calcutta When built 1826
 By whom built — Owners Seyon
 Port belonging to London Destined Voyage Amman
 If Surveyed Afloat or in Dry Dock Kings Dock

Original Survey, No. — Dated — Classed 12 F, 1
 Port —

Repairs. At the present time the two upper strokes of
 good Sheathing taken off caulked under and
 replaced with new, Sheathing with yellow Metal
 to the wales,

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting <u>good</u>	Wales	Masts, Yards, &c. <u>good</u>
Plank Shears	Counter <u>good</u>	Sails <u>Sufficient</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

The upper strokes of sheathing was taken
 off to by the caulking of the main bottom which
 proved good she is in the most efficient
 condition fit for the conveyance of any perishable
 cargo to from all parts of the world and may be

The Amount of Fee.....£ : : is received by me,

Classed X F, 1

Committee's Minute 18

Character assigned —