

REPORT of SURVEY for REPAIRS.

No. 6507 Survey held at London Date Aug 25 1837
on the Back? Querscutt Master A Riddell
Tonnage 366 Built at Sunderland When built 1835
By whom built Lanig Owners Heisch & Co
Port belonging to London Destined Voyage Sydney
If Surveyed Afloat or in Dry Dock Up^d Doreous Dry Dock

Original Survey, No. _____ Dated 1835 Classed 11A1
Port London

Repairs. at the present time stripped, caulked from keel to wale
& generally overhauled & Coppered

The Surveyor to state the present Condition of	
Upper Deck Fastenings <u>Good</u>	Wales <u>Good</u>
Spirkettling <u>"</u>	Counter <u>"</u>
Plank Shears <u>"</u>	Plank and Treennails <u>"</u> (Outside to the Water's Edge)
Topsides <u>"</u>	Rudder <u>"</u>
Upper Deck with its Appendages <u>"</u>	Windlass <u>"</u>
Lower Deck Fastenings <u>"</u>	Capstan <u>"</u>

General Observations and Opinion, Best Sails, Rigging Anchors & Hables good -
In my opinion this vessel is fully entitled
as required by the Instructions, to remain in her present class 11A1

George Bayley

The Amount of Fee..... £ : : is received by me.

Committee Minute _____ 183 _____

Character assigned _____