

Coffering

REPORT of SURVEY for REPAIRS.

No. 6533 Survey held at London Date June 8 1840
 on the B^{ty} Betty Sarah Master W. Brown
 Tonnage 167 Built at London When built 1825
 By whom built _____ Owners J. Beish
 Port belonging to London Destined Voyage Leghorn
 If Surveyed Afloat or in Dry Dock breastway

Original Survey, No. _____ Dated 1837 Classed Cont 4 Jan 1836
 Port London

Repairs Stipped caulked keel up and resheathed
with yellow elm to same height
as before

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

Good *Good* *Good*

General Observations and Opinion,
 as required by the Instructions, In my opinion this vessel is at present
eligible to remain as classed A1
George Bayley

The Amount of Fee.....£ : : is received by me,

Committee's Minute _____ 18

Character assigned _____