

ANNUAL SURVEYS.

No. 606 Survey held at London Date August 6th 1840
on the Barque Lord Lowther Master —
Tonnage 1425 Built at London When built 1826
By whom built Wm. Barnard Owners Tomlin
Port belonging to London Destined Voyage India
Surveyed Abd. W. in Dry Dock Mr. Pitchers dock

Original Survey, No. 14532 Port of London Classed 12 A 1
Cont 38; 4 In

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>—</u>	Capstan <u>—</u>
Upper Deck Beams & Fastenings <u>—</u>	Transoms <u>Good were seen</u>	Pumps <u>—</u>
Lower Deck Beams & Fastenings <u>—</u>	Timbers of the Frame <u>—</u>	Masts, Yards, &c. <u>—</u>
Spirketting <u>Good</u>	Topsides <u>some defective planks in the Sheer Strakes</u>	Sails <u>Good & efficient</u>
Plank Shears <u>—</u>	Wales <u>fair sound state</u>	Cables <u>—</u>
Waterways <u>—</u>	Plank and Treenails <u>—</u> (Outside to the Water's Edge.)	Anchors No. of <u>—</u>
Hatchway Comings <u>—</u>	Rudder <u>Good</u>	Standing & Running Rigging <u>—</u>
	Windlass <u>—</u>	Copper <u>—</u>

General Observations and Opinion, At the present time, Repaired the Copper, Caulked the Ship all
as required by the Instructions, from the Copper over the ship's 2 broken upper deck knees; fitted a short piece of false
stem and Gripe, (the lower piece of stem is badly wounded)
Recommended to shift the lower piece of stem, & 2 planks in the Sheer
Strakes on each side which are defective round, the upper deck fastenings,
and in my opinion she is not eligible to remain as a ship.

Committee Minute 18th August 1840

Character assigned See back of Survey

Before the repairs were commenced notice in writing was given to the owners & they agreed that the lower piece of stem should be shifted & to shift some of the Sheer Strakes & Gripe.

LON 608-0246

August 18. 1840. I am informed that nothing was
done to the stem beyond getting some small
pieces on the edge - and that the gripe was
secured by straps - I presume in consequence
of the apprehended insecurity of the bolts in
the stem - George Bayley

AB It does not appear that any planks were shifted -

L. 14 Aug to the owner

Genl Comdr

27 August 1840.

Ordered that unless the requisition
of the Surgeon be complied with, the
charact be exposed - write to owner

L. 27 Aug
to 3 Sept

Genl Comdr

3 Sept 1840

Charact to be exposed -



© 2019

Lloyd's Register
Foundation