

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date 1 March 1836
on the Ship Ralph Bernal Master Pue
Tonnage 314 Built at Sunderland When built 1835
By whom built Hutchinson Owners MacKays
Port belonging to London Destined Voyage Jamaica
If Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 336 Dated London

Port _____

Repairs. March 1836 - Caulked and Coppered Seams
to both Beams

General Observations
and Opinion, as
required by the
Instructions.

refer to previous report Mr Bayley

Continued

The Amount of Fee £ : : is received by me.

Committee Minute _____ 183 _____

Character assigned _____