

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date March 6 1836
 on the Bark Ralph Bernal Master _____
 Tonnage 31 1/4 Built at Sunderland When built 1835
 By whom built Mitchinson Owners _____
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Ship at Hawks & Dry Dock,

Original Survey, No. _____ Dated October 1835 Chapin 1141?
 Port Sunderland

Repairs. At the present time has been caulked from the keel up and coppered up on Paper.

General Observations
 and Opinion, as
 required by the
 Instructions

Some additional fastenings to the Brack by
A Crutch was put in whilst laying in
Ship at Hawks & Dry Dock at my suggestion
She is in good and efficient condition &
entitled to her present class
George Bayley

27 Fee

The Amount of Fee.....£ : : is received by me.

Committee Minute _____ 183 _____

Character assigned _____