

# ANNUAL SURVEYS.

6682

No.          Survey held at London Date August 31<sup>st</sup> 1840  
 on the Ship Malmer Castle Master Gimlett  
 Tonnage 656 Built at London When built 1836  
 By whom built John Williams & Sons Owners R. G. G. G.  
 Port belonging to          Destined Voyage           
 If Surveyed Afloat or in Dry Dock Blackwall Yard

Original Survey, No. 4697, 5481 Port of London Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, as required by the Instructions, At the present time Caulked from the Copper & 2 Waterways. Repaired the ~~top~~ yellow metal  
The ship is in a very efficient state, and may remain as claps up

Committee Minute 8<sup>th</sup> Septe 1840  
 Character assigned 12 A 1  
Nathl. Clark

No. 450 Survey held at London Date Sept 2<sup>nd</sup> 1840  
 on the Brig "Tyne" Master Prismar  
 Tonnage 316 Built at Shields When built 1824  
 By whom built          Owners Forrest & Co  
 Port belonging to London Destined Voyage London  
 If Surveyed Afloat or in Dry Dock Mr. Fletcher's way

Original Survey, No. 549, 2304 Port of London Classed A 1  
3618, 4582, 5427, 5826,

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank & Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, as required by the Instructions, At the present time; fitted a middle piece, and 2  
clamps in lower deck beams. The ship appears to  
stand fast, at the beam ends; and looks in a sound state  
and may remain as claps up

Committee Minute 8<sup>th</sup> Septe 1840  
 Character assigned A 1 Asterisk  
Nathl. Clark