

REPORT of SURVEY for REPAIRS.

Change of Owners 6/38
AD

No. _____ Survey held at London Date 17th Sept 1840
 on the By Charlotte Mylic Master W. Walker
 Tonnage 150 Built at Poole When built 1821
 By whom built _____ Owners J. Stutton
 Port belonging to London Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. ²³⁰⁷ 2308, 3625 Dated _____ Classed FI
 Port London 4670, 4705,

Repairs

Overhauled

The Surveyor is also required to state the present Condition of the

Decks _____	Transoms _____	Windlass _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Capstan _____
Lower Deck Beams & Fastenings _____	Topsides _____	Pumps _____
Spirkettling _____	Wales _____	Masts, Yards, &c. <u>Insufficient</u>
Plank Shears _____ <u>good</u>	Counter _____ <u>good</u>	Sails _____ <u>good</u>
Waterways _____	Plank and Treenails <small>(Outside to the Water's Edge)</small> _____	Cables _____
Hatchway Comings _____	Rudder _____	Anchors No. of _____
Breasthooks _____	Copper _____	Standing & Running Rigging _____

General Observations and Opinion, as required by the Instructions, Is in good and efficient condition fit for the carriage of dry and perishable cargo and may be continued as classed

W. Walker
W. Walker

The Amount of Fee.....£ / : — : — is received by me, W. Walker

Committee's Minute 25th Sept 1840

Character assigned FI AD