

REPORT of SURVEY for REPAIRS.

6763.

No. 924 Survey held at London Date Sep 30th 1840
 on the Baque Eliza Stewart Master Miller
 Tonnage 423 Built at Glenock When built 1833
 By whom built Owners Stewart
 Port belonging to Glasgow Destined Voyage Sydney
 Surveyed At or in Dry Dock Ship^r Hatchers

Original Survey, No. 5377 Dated Classed NA1
 Port London

Repairs

At the present time stripped off the Copper. Many
 the Ship caulked the Bottom. Iron Sheathing on the
 Upper Course over Bonairides felt, and re-coppered the Bottom

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

This ship appears in a very good state. fit for
 the safe conveyance of our and perishable goods to and from
 all parts of the world, and in my opinion may remain as
 closed

The Amount of Fee.....£ : : is received by me,

Committee's Minute 2nd October 1840

Character assigned 10 A