

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date 16 Oct 18 39
 on the Ship Superior Master Walker
 Tonnage 270 Built at Bermuda When built 1826
 By whom built _____ Owners Sutherland & Co
 Port belonging to Minevent Destined Voyage Per cent
 If Surveyed Afloat or in Dry Dock _____

Original Survey, No. _____ Dated _____ Classed A1
 Port _____

Repairs

New plank of the Deck next the waterway
 run over board

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

Is in good and efficient condition
 fit for the conveyance of my own private cargo &
 may be continued as before

The Amount of Fee.....£ : : is received by me,

Committee's Minute _____ 18

Character assigned _____