

ANNUAL SURVEYS.

68146
999
775

No. 116 Survey held at Liver Date Oct 17th 1842
 on the 19th Sur. Dickers Master Thomas
 Tonnage 124 Built at Liverpool When built 1810
 By whom built _____ Owners Withams
 Port belonging to Liver Destined Voyage Duties
 If Surveyed Afloat or in Dry Dock in the Way

Original Survey, No. 34, 2012 Port of Liver 1039 Classed F, 1
4970

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Good</u>	Capstan _____
Upper Deck Beams & Fastenings <u>Fair</u>	Transoms <u>"</u>	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame <u>sound when seen</u>	Masts, Yards, &c. _____
Spirkettling <u>Good</u>	Topsides <u>Good</u>	Sails <u>Good</u>
Plank Shears _____	Wales <u>"</u>	Cables _____
Waterways _____	Plank and Treennails (Outside to the Water's Edge) <u>"</u>	Anchors No. of <u>Sufficient</u>
Hatchway Comings _____	Rudder <u>"</u>	Standing & Running Rigging _____
	Windlass <u>"</u>	Copper _____

General Observations and Opinion, At the present time new Hog Ties, one new plank in
as required by the instructions, the Masts, several new Treennails, caulked & general
overhaul, has a very firm appearance and is fit
for the safe conveyance of dry & perishable cargoes
she may remain her present Way

Committee Minute 6th Nov 1842
 Character assigned F, 1
W. Withams

No. 206 Survey held at Liver Date October 17th 1840
 on the 19th Robert Allen Master S. Bunt
 Tonnage 116 Built at New Brunswick When built 1830
 By whom built _____ Owners Seaton & Co
 Port belonging to Liver Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 5379 Port of Liver 1039 Classed A, 1

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkettling <u>Good</u>	Topsides _____	Sails <u>Good</u>
Plank Shears _____	Wales <u>Good</u>	Cables _____
Waterways _____	Plank and Treennails (Outside to the Water's Edge) _____	Anchors No. of <u>Sufficient</u>
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper _____

General Observations and Opinion, Very good condition and well found in every
as required by the instructions, and may be classed A, 1

Committee Minute 6th Nov 1841
 Character assigned A, 1
W. Withams