

# ANNUAL SURVEYS.

6860

No. 283 Survey held at London Date 10. Nov<sup>r</sup> 1840  
 on the By Alton Master Champion  
 Tonnage 178 Built at Newcastle When built 1779  
 By whom built London Owners Edwards & Co  
 Port belonging to London Destined Voyage Cadiz  
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 1837, 470 Port of London  
1831

Classed 1838 5th  
1841

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting <u>good</u>	Topsides <u>good</u>	Sails <u>Sufficient</u>
Plank Shears	Wales	Cables <u>11</u>
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of <u>10</u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,  
 as required by the Instructions,

It is in good and efficient condition  
and may be recommended as capable  
of performing the service

Committee Minute 13th Nov 1840

Character assigned 1st 3A

No. 261 Survey held at London Date 9. Nov<sup>r</sup> 1840  
 on the By Northen Master Craig  
 Tonnage 122 Built at Stephens When built 1776  
 By whom built London Owners Miles  
 Port belonging to London Destined Voyage Granada  
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 597 Port of London  
2393, 3506, 3707, 4190, 4576

Classed 1847

The Surveyor is required to state the present Condition of the

Decks <u>Sufficiently repaired</u>	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting <u>good</u>	Topsides <u>good</u>	Sails <u>Sufficient</u>
Plank Shears	Wales	Cables <u>11</u>
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,  
 as required by the Instructions,

It is in good and efficient condition  
and may be recommended as capable  
of performing the service

Committee Minute 13th Nov 1840

Character assigned 1st 3A