

REPORT of SURVEY for REPAIRS.

6067

No. _____ Survey held at London Date 27. 26. 27. 31 18 82
 on the Beauchief Master Nov 11
 Tonnage 425 Built at Swiss When built 1828
 By whom built _____ Owners H. Allan
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Swiss Dock

Original Survey, No. 1205, 2406 Dated March 1855 Classed A.1 S.S. 2. 5. 1
3211, 4950, 5061,
 Port London

Repairs At the present time in consequence of having been ashore shipped, 6 long pieces 11 long pieces shifted & 15 refitted & 8 short beams shifted - 2 brim top fitted over Port after caulking from the keel up over all. Totted and sheathed and all the damage repaired - The timbers exposed where the beams were shifted are very good -

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Keel	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, In my opinion the ship is eligible to remain as classed A.1
George Dugby

The Amount of Fee £ 2 : - : - is received by me.
 Committee's Minute 17th Nov 1882
 Character assigned A.1