

ANNUAL SURVEYS.

6875

No. 40 Survey held at London Date Nov 17 1840
 on the B. B. Baskale Master Pick
 Tonnage 144 Built at Whitchurch When built 1837
 By whom built _____ Owners Thos & Co
 Port belonging to Whitchurch Destined Voyage _____
 If Surveyed Afloat or in Dry Dock gun Dock & dry

Original Survey, No. 77 Port of Whitchurch 1837 Classed 741

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>good & smooth</u>

General Observations and Opinion,
 as required by the Instructions,

The vessel appears to be in good order & eligible to remain as classed 741

Committee Minute 20th Nov 1840

Character assigned

741

George Barclay

No. 507 Survey held at London Date Nov 17 1840
 on the Boat Antistate Master Bales
 Tonnage 140 Built at Lancaster When built 1820
 By whom built _____ Owners Phillips
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock gun Dock

Original Survey, No. 1812, 2461 Port of London Jan 1840 Classed F.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>up & good</u>

General Observations and Opinion,
 as required by the Instructions,

Consequence of being struck by lightning has been shewn by caulking over copper up - in my opinion it is eligible to remain as classed F.1

Committee Minute 20th Nov 1840

Character assigned

741

George Barclay