

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date May 31 1859
 on the Ship Madagascar Master Walker?
 Tonnage 35 Built at London When built 1837
 By whom built Green Owners R Green
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Blackwall Dry Dock,

Original Survey, No. 4895 Dated Nov 1858 Classed 12 A-1
 Port London 2nd classed 1860

Repairs At the present time masts, carried from the keel up over
all and generally overhauled. and re-sheeted with
yellow metal

This vessel presents a very firm appearance and
is free from any indication of movement at the Postways
& beam ends.

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>1859</u>	Standing & Running Rigging

General Observations and Opinion, In my opinion this ship is entitled to remain as classed
 as required by the Instructions.

The Amount of Fee.....£ : : is received by me,

Committee Minute 24th Nov 1859

Character assigned Recd