

REPORT of SURVEY for REPAIRS.

No. ⁶⁹¹⁴ Survey held at London Date May 31st 1857
 on the Ship Malabar Master Tucker
 Tonnage 647 Built at London When built 1834
 By whom built Green & Co Owners A. Green
 Port belonging to London Destined Voyage Albion
 If Surveyed Afloat or in Dry Dock Blackwall Dry Dock

Original Survey, No. _____ Dated 1835 Chapl 12 A1
 Port London

Repairs.

*At the present time stipples, caulked from the keel up
 and sheathed with yellow metal upon paper
 New Foremast all the other overhauled*

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
 Spirketting _____
 Plank Shears _____
 Topsides _____
 Upper Deck with its Appendages _____
 Lower Deck Fastenings _____

Wales _____
 Counter _____
 Plank and Treennails
(Outside to the Water's Edge.) _____
 Rudder _____
 Winlass _____
 Capstan _____

Part of overhauling

General Observations and Opinion,
 as required by the Instructions,

*This vessel is in my opinion entitled to
 remain classed*


 George Darby

The Amount of Fee.....£ : is received by me.

Committee Minute _____ 183 _____

Character assigned _____



Lloyd's Register Foundation