

REPORT of SURVEY for ~~REPAIRS~~ ^{Suppering}

6915

No. 224 Survey held at Sunder Date Decr 20th 1839
 on the V^o Maria Master J. Briggs
 Tonnage 146 Built at Shoreham When built 1835
 By whom built _____ Owners Travers & Co
 Port belonging to Sunder Destined Voyage Constantinople
 If Surveyed Afloat or in Dry Dock Sunder Dock

Original Survey, No. 13 Dated 1836 Classed 1A1
 Port of Sunder Shoreham

Repairs In August 1830 Bottom studded, caulked, and Clefford was papered

The Surveyor is also required to state the present Condition of the

| | | |
|-------------------------------|---|-------------------------------|
| Decks | Transoms | Windlass |
| Upper Deck Beams & Fastenings | Timbers of the Frame | Capstan |
| Lower Deck Beams & Fastenings | Topsides | Pumps |
| Spirkettling | Wales | Masts, Yards, &c. <u>good</u> |
| Plank Shears | Counter | Sails <u>efficient</u> |
| Waterways | Plank & Treenoils <small>(outside to the Water's Edge)</small> | Cables |
| Hatchway Casings | Rudder | Anchors No. of |
| Breasthooks | Copper | Standing & Running Rigging |

General Observations and Opinion, Ship is very efficient state and may continue as required by the Instructions.



© 2019

The Amount of Fee £ : : is received by me, Lloyd's Register Foundation
 Committee's Minute On the 11th 1840
 Character assigned 1A1